

Published July 10th, 2019

Broken water main causes minor detour on Canyon Road

By Vera Kochan



EBMUD patched intersection's ruptured water main caused by Verizon contractor Photo Vera Kochan

underground East Bay Municipal Utility District water main resulting in the temporary closure."

ITC Service Group's website states that they provide "design, broadband, wireless and technical staffing services to telecom and information communication technology sectors within the communications industry."

When asked who is responsible for any damages the town may have incurred, Chan said, "It has not been determined yet who is responsible for the EBMUD damage, but since ITC Service Group has an encroachment permit with the Town, they will be responsible for the cost accrued by the Town."

Reach the reporter at: vera@lamorindaweekly.com

[back](#)

Copyright © Lamorinda Weekly, Moraga CA